

A1.5 Power Amplifier changelog

Firmware v 1.1

- More robust startup sequence to avoid some cases where the A1.5 needs 2 times to start